


Condor Circuit Plan



Planned Work:

- New insulated wire has already been installed on nearly all existing overhead portions of the circuit
- Replace an additional 1.7 miles of existing overhead wire with new insulated wire near the substation

Expected Improvements:

- **51% reduction** in customer outage time, assuming the same weather conditions in 2020